


Chapter 11-13: Metal Alloys and Ceramics Applications and Processing

ISSUES TO ADDRESS...

- How are metal alloys classified and how are they used?
 - What are some of the common fabrication techniques?
 - How can properties be modified by post heat treatment
-
- Structures of ceramic materials
 - Point defects, impurities, types of ceramic
 - Processing and applications



Taxonomy of Metals




Adapted from Fig. 11.1, Callister 7e.

Adapted from Fig. 9.24, Callister 7e. (Fig. 9.24 adapted from *Binary Alloy Phase Diagrams*, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)



Steels





increasing strength, cost, decreasing ductility


Based on data provided in Tables 11.1(b), 11.2(b), 11.3, and 11.4, Callister 7e.




Refinement of Steel from Ore




heat generation



reduction of iron ore to metal



purification



Ferrous Alloys

Iron containing – Steels - cast irons

Nomenclature AISI & SAE

10xx Plain Carbon Steels

11xx Plain Carbon Steels (resulfurized for machinability)

15xx Mn (10 ~ 20%)

40xx Mo (0.20 ~ 0.30%)

43xx Ni (1.65 - 2.00%), Cr (0.4 - 0.90%), Mo (0.2 - 0.3%)

44xx Mo (0.5%)

where xx is wt% C x 100

example: 1060 steel – plain carbon steel with 0.60 wt% C

Stainless Steel -- >11% Cr



Cast Iron


- Ferrous alloys with > 2.1 wt% C
 - more commonly 3 - 4.5 wt% C
- low melting (also brittle) so easiest to cast
- Cementite decomposes to ferrite + graphite
$$\text{Fe}_3\text{C} \rightarrow 3 \text{Fe} (\alpha) + \text{C} (\text{graphite})$$
 - generally a slow process



Fe-C True Equilibrium Diagram

Graphite formation promoted by

- Si > 1 wt%
- slow cooling



Adapted from Fig. 11.2, Callister 7e. (Fig. 11.2 adapted from *Binary Alloy Phase Diagrams*, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)



Types of Cast Iron

Gray iron


- graphite flakes
- weak & brittle under tension
- stronger under compression
- excellent vibrational dampening
- wear resistant



Adapted from Fig. 11.3(a) & (b), *Callister 7e*.

Ductile iron

- add Mg or Ce
- graphite in nodules not flakes
- matrix often pearlite - better ductility



Types of Cast Iron

White iron


- <1wt% Si so harder but brittle
- more cementite



Adapted from Fig. 11.3(c) & (d), *Callister 7e*.



Malleable iron

- heat treat at 800-900°C
- graphite in rosettes
- more ductile



Production of Cast Iron

Adapted from Fig.11.5,
Callister 7e.



Limitations of Ferrous Alloys

- 1) Relatively high density
- 2) Relatively low conductivity
- 3) Poor corrosion resistance



Nonferrous Alloys

• Cu Alloys

Brass: Zn is subst. impurity (costume jewelry, coins, corrosion resistant)

Bronze: Sn, Al, Si, Ni are subst. impurity (bushings, landing gear)

Cu-Be: precip. hardened for strength

• Ti Alloys

-lower ρ : 4.5g/cm³
vs 7.9 for steel
-reactive at high T
-space applic.

NonFerrous Alloys

• Al Alloys

-lower ρ : 2.7g/cm³
-Cu, Mg, Si, Mn, Zn additions
-solid sol. or precip. strengthened (struct. aircraft parts & packaging)

• Mg Alloys

-very low ρ : 1.7g/cm³
-ignites easily
-aircraft, missiles


• Refractory metals


-high melting T
-Nb, Mo, W, Ta

• Noble metals

-Ag, Au, Pt
-oxid./corr. resistant







Metal Fabrication

- How do we fabricate metals?
 - Blacksmith - hammer (forged)
 - Molding - cast
- Forming Operations
 - Rough stock formed to final shape

The shape of a metal piece is changed by plastic deformation

Hot working

vs.

Cold working

- T high enough for recrystallization
- Larger deformations possible
- Deformation energy are less
- some surface oxidation.

- well below T_m
- the strain hardens
- smaller deformations
- high quality surface finish




Metal Fabrication Methods - I

FORMING


CASTING

JOINING

- Forging (Hammering; Stamping) (wrenches, crankshafts)




- Drawing (rods, wire, tubing)




die must be well lubricated & clean

- Rolling (Hot or Cold Rolling) (I-beams, rails, sheet & plate)



Adapted from Fig. 11.8, Callister 7e.

- Extrusion (rods, tubing)



ductile metals, e.g. Cu, Al (hot)



Metal Fabrication Methods - II



- **Casting**- mold is filled with metal
 - metal melted in furnace, perhaps alloying elements added. Then **cast** in a mold
 - most common, cheapest method
 - gives good production of shapes: large or complicated shapes
 - weaker products, internal defects
 - good option for brittle materials



Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- Sand Casting

(large parts, e.g., auto engine blocks, fire hydrants, large pipe fittings)




- trying to hold something that is hot
- what will withstand $>1600^{\circ}\text{C}$?
- cheap - easy to mold => sand!!!
- pack sand around form (pattern) of desired shape

Metal Fabrication Methods - II



- **Sand Casting**


(large parts, e.g., auto engine blocks)



- **Investment Casting**

(low volume, complex shapes e.g., jewelry, turbine blades)

plaster die formed around wax prototype



- **Investment Casting (lost-wax)**

- pattern is made from paraffin or wax.
- mold made by encasing in plaster of paris
- melt the wax & the hollow mold is left
- pour in metal



Metal Fabrication Methods - II


FORMING

CASTING

JOINING

- Sand Casting


(large parts, e.g., auto engine blocks)



- Investment Casting

(low volume, complex shapes e.g., jewelry, turbine blades)


plaster die formed around wax prototype



- Die Casting


(high volume, low T alloys)

Steel mold or die



- Continuous Casting

(simple slab shapes)




Metal Fabrication Methods - III

FORMING


CASTING

JOINING

- **Powder Metallurgy**
(materials w/low ductility or high melting temperature)



- **Welding**
(when one large part is impractical)



- **Heat affected zone:**
(region in which the microstructure has been changed).


Adapted from Fig. 11.9, *Callister 7e*.
(Fig. 11.9 from *Iron Castings Handbook*, C.F. Walton and T.J. Opar (Ed.), 1981.)




Gas and arc welding, or Laser beam welding

Thermal Processing of Metals

Annealing: Heat to T_{anneal} , then cool slowly.






Heat Treatments

- a) Annealing
- b) Quenching
- c) Tempered Martensite

Adapted from Fig. 10.22, Callister 7e.



Summary-metal alloy

- Steels: increase TS , Hardness (and cost) by adding
 - C (low alloy steels)
 - Cr, V, Ni, Mo, W (high alloy steels)
 - ductility usually decreases w/additions.
- Non-ferrous:
 - Cu, Al, Ti, Mg, Refractory, and noble metals.
- Fabrication techniques:
 - forming, casting, joining.
- Thermal treatment



Ceramics

Traditional ceramics: china, porcelain, bricks, tiles, glass, etc.



Ceramic Bonding

- Interatomic Bonding:
 - Mostly ionic, some covalent.
 - % ionic character increases with difference in electronegativity.

$$\% \text{ ionic character} = \{1 - \exp[-(0.25)(X_A - X_B)^2]\} \times 100$$
- Large vs small ionic bond character:

IA																		0
H																		He
2.1	IIA											IIIA	IVA	VA	VIA	VIIA		-
Li	Be											B	C	N	O	F		Ne
1.0	1.5											2.0	2.5	3.0	3.5	4.0		-
Na	Mg											Al	Si	P	S	Cl		Ar
0.9	1.2	IIIB	IVB	VB	VIB	VIIIB	VIII			IB	IIB	1.5	1.8	2.1	2.5	3.0		-
K	Ca	Sc	Ti	V	Cr	Mn	Fe	Co	Ni	Cu	Zn	Ga	Ge	As	Se	Br		Kr
0.8	1.0	1.3	1.5	1.6	1.6	1.5	1.8	1.8	1.8	1.9	1.6	1.6	1.8	2.0	2.4	2.8		-
Rb	Sr	Y	Zr	Nb	Mo	Tc	Ru	Rh	Pd	Ag	Cd	In	Sn	Sb	Te	I		Xe
0.8	1.0	1.2	1.4	1.6	1.8	1.9	2.2	2.2	2.2	1.9	1.7	1.7	1.8	1.9	2.1	2.5		-
Cs	Ba	La-Lu	Hf	Ta	W	Re	Os	Ir	Pt	Au	Hg	Tl	Pb	Bi	Po	At		Rn
0.7	0.9	1.1-1.2	1.3	1.5	1.7	1.9	2.2	2.2	2.2	2.4	1.9	1.8	1.8	1.9	2.0	2.2		-
Fr	Ra	Ac-No																
0.7	0.9	1.1-1.7																

CaF₂: large

SiC: small

Adapted from Fig. 2.7, Callister 7e.

Most ceramics are compounds between metallic and nonmetallic elements



Ionic Crystals

Table 12.1 For Several Ceramic Materials, Percent Ionic Character of the Interatomic Bonds

<i>Material</i>	<i>Percent Ionic Character</i>	<u>Cation Radius (nm)</u>	<u>Anion Radius (nm)</u>
CaF ₂	89	0.100	0.133
MgO	73	0.072	0.14
NaCl	67	0.102	0.182
Al ₂ O ₃	63	0.053	0.140
SiO ₂	51	0.040	0.140
Si ₃ N ₄	30		
ZnS	18		
SiC	12		

Note: larger anion radius



Cations: metallic ions, positively charged

Anions: nonmetallic ions, negatively charged

Crystal structure {

- The magnitude of the electrical charge on each of the component ions
- The relative sizes of the cations and anions

Most ionic crystals can be considered as close-packed structure of anions with cations in the interstitial sites.



Ceramic Crystal Structures

Oxide structures

- oxygen anions much larger than metal cations
- close packed oxygen in a lattice (usually FCC)
- cations in the holes of the oxygen lattice



Site Selection

Which sites will cations occupy?

1. Size of sites

- does the cation fit in the site

for each cation prefers to have as many nearest-neighbor anion; the anions also desire a maximum number of cation nearest neighbors.

2. Stoichiometry

- if all of one type of site is full, the remainder have to go into other types of sites.


3. Bond Hybridization




Ionic Bonding & Structure

1. Size - Stable structures:


--maximize the # of nearest oppositely charged neighbors.



unstable



stable




stable

Adapted from Fig. 12.1,
Callister 7e.

- Charge Neutrality:

--Net charge in the structure should be zero.



--General form: $A_m X_p$

m, p determined by charge neutrality





Coordination # and Ionic Radii

- Coordination # increases with $\frac{r_{\text{cation}}}{r_{\text{anion}}}$
- Issue:** How many anions can you arrange around a cation?


$\frac{r_{\text{cation}}}{r_{\text{anion}}}$	Coord #	
< 0.155	2	linear
0.155 - 0.225	3	triangular
0.225 - 0.414	4	T_D
0.414 - 0.732	6	O_H
0.732 - 1.0	8	cubic

Adapted from Table 12.2, Callister 7e.




ZnS
(zincblende)

Adapted from Fig. 12.4, Callister 7e.



NaCl
(sodium chloride)

Adapted from Fig. 12.2, Callister 7e.



CsCl
(cesium chloride)

Adapted from Fig. 12.3, Callister 7e.



Cation-anion stable configuration






FIGURE 12.1 Stable and unstable anion–cation coordination configurations. Open circles represent anions; colored circles denote cations.

e.g. computation of minimum $\frac{r_C}{r_A}$ for a 3-coordinate

when $\cos \alpha = \frac{r_A}{r_A + r_C}$



Rewrite as

$$\frac{r_C}{r_A} = \frac{1}{\cos \alpha} - 1$$

With $\alpha = 30^\circ$


$$\frac{r_C}{r_A} = 0.155$$

Minimum ratio for 3-coordinate



Cation Site Size

- Determine minimum $r_{\text{cation}}/r_{\text{anion}}$ for O_H site (C.N. = 6)



$$2r_{\text{anion}} + 2r_{\text{cation}} = 2\sqrt{2}r_{\text{anion}}$$

$$r_{\text{anion}} + r_{\text{cation}} = \sqrt{2}r_{\text{anion}} \quad r_{\text{cation}} = (\sqrt{2} - 1)r_{\text{anion}}$$

$$\frac{r_{\text{cation}}}{r_{\text{anion}}} = 0.414$$



Site Selection II

2. Stoichiometry

- If all of one type of site is full, the remainder have to go into other types of sites.

Ex: FCC unit cell has 4 O_H and 8 T_D sites.

If for a specific ceramic each unit cell has 6 cations and the cations prefer O_H sites

4 in O_H

2 in T_D



Site Selection III

3. **Bond Hybridization** – significant covalent bonding
- the hybrid orbitals can have impact if significant covalent bond character present
 - For example in SiC
 - $X_{\text{Si}} = 1.8$ and $X_{\text{C}} = 2.5$

$$\% \text{ ionic character} = 100 \{1 - \exp[-0.25(X_{\text{Si}} - X_{\text{C}})^2]\} = 11.5\%$$

- ca. 89% covalent bonding
- both Si and C prefer sp^3 hybridization
- Therefore in SiC get T_D sites



Example: Predicting Structure of FeO

- On the basis of ionic radii, what crystal structure would you predict for FeO?

Cation Ionic radius (nm)

Al³⁺ 0.053

Fe²⁺ 0.077

Fe³⁺ 0.069

Ca²⁺ 0.100

Anion

O²⁻ 0.140

Cl⁻ 0.181

F⁻ 0.133

- Answer:

$$\frac{r_{\text{cation}}}{r_{\text{anion}}} = \frac{0.077}{0.140} = 0.550$$

based on this ratio,

--coord # = 6




--structure = NaCl

Data from Table 12.3,
Callister 7e.



Rock Salt Structure

Same concepts can be applied to ionic solids in general.
Example: NaCl (rock salt) structure




$$r_{\text{Na}}/r_{\text{Cl}} = 0.564$$

∴ cations prefer O_H sites

Adapted from Fig.
12.2, *Callister 7e*.

MgO and FeO

MgO and FeO also have the NaCl structure



$$r_{\text{Mg}}/r_{\text{O}} = 0.514$$

∴ cations prefer O_{H} sites

Adapted from Fig.
12.2, Callister 7e.



So each oxygen has 6 neighboring Mg²⁺

ABX₃ Crystal Structures

- Perovskite

Ex: complex oxide
BaTiO₃

Adapted from Fig.
12.6, *Callister 7e*.



Mechanical Properties


We know that ceramics are more brittle than metals. **Why?**

- Consider method of deformation
 - slippage along slip planes
 - in ionic solids this slippage is very difficult
 - too much energy needed to move one anion past another anion





Silicate Ceramics


Most common elements on earth are Si & O



SiO_4^{4-} tetrahedron



Adapted from Figs. 12.9-10, Callister 7e.




- SiO_2 (silica) polymorphic crystalline structures are quartz, cristobalite, & tridymite
- The strong Si-O bond leads to a strong, high melting material (1710°C)



Amorphous Silica

- Silica gels - amorphous SiO_2
 - Si^{4+} and O^{2-} not in well-ordered lattice
 - Charge balanced by H^+ (to form OH^-) at “dangling” bonds
 - very high surface area $> 200 \text{ m}^2/\text{g}$
 - SiO_2 is quite stable, therefore unreactive
 - makes good catalyst support



Adapted from F
12.11, Callister




Silica Glass

- Dense form of amorphous silica
 - Charge imbalance corrected with “counter cations” such as Na^+
 - Borosilicate glass is the pyrex glass used in labs
 - better temperature stability & less brittle than sodium glass
 - In addition to the quartz, sodium carbonate, and calcium carbonate traditionally used in glassmaking, boron is used in the manufacture of borosilicate glass. Typically, the resulting glass composition is about 70% silica, 10% boric oxide, 8% sodium oxide, 8% potassium oxide, and 1% calcium oxide (lime).
 - Borosilicate glass begins to soften around 821 °C




Layered Silicates


- Layered silicates (clay silicates)
 - SiO_4 tetrahedra connected together to form 2-D plane



- $(\text{Si}_2\text{O}_5)^{2-}$
- So need cations to balance charge



=




Adapted from Fig. 12.13, Callister 7e.



Layered Silicates

- Kaolinite clay alternates $(\text{Si}_2\text{O}_5)^{2-}$ layer with $\text{Al}_2(\text{OH})_4^{2+}$ layer



Adapted from Fig. 12.14, *Callister 7e*.

Note: these sheets loosely bound by van der Waal's forces




Layered Silicates

- Can change the counterions
 - this changes layer spacing
 - the layers also allow absorption of water
- Micas $\text{KAl}_3\text{Si}_3\text{O}_{10}(\text{OH})_2$
 - smooth surface for AFM sample holder
- Bentonite
 - used to seal wells
 - packaged dry
 - swells 2-3 fold in H_2O
 - pump in to seal up well so no polluted ground water seeps in to contaminate the water supply.



Carbon Forms

- Carbon black – amorphous – surface area ca. 1000 m²/g
- Diamond
 - tetrahedral carbon
 - hard – no good slip planes
 - brittle – can cut it
 - large diamonds – jewelry
 - small diamonds
 - often man made - used for cutting tools and polishing
 - diamond films
 - hard surface coat – tools, medical devices, etc.




Adapted from Fig. 12.15, *Callister 7e*.



Carbon Forms - Graphite




- layer structure – aromatic layers



Adapted from Fig.
12.17, *Callister 7e*.


- weak van der Waal's forces between layers
- planes slide easily, good lubricant

Carbon Forms - Graphite




Carbon Forms – Fullerenes and Nanotubes


- Fullerenes or carbon nanotubes
 - wrap the graphite sheet by curving into ball or tube
 - Buckminster fullerenes
 - Like a soccer ball C_{60} - also C_{70} + others



Adapted from Figs.
12.18 & 12.19,
Callister 7e.




Graphene



Defects in Ceramic Structures

- Frenkel Defect
--a cation is out of place.
- Shottky Defect
--a paired set of cation and anion vacancies.



Adapted from Fig. 12.21, *Callister 7e*. (Fig. 12.21 is from W.G. Moffatt, G.W. Pearsall, and J. Wulff, *The Structure and Properties of Materials*, Vol. 1, *Structure*, John Wiley and Sons, Inc., p. 78.)


- Equilibrium concentration of defects $\sim e^{-Q_D / kT}$

Impurities


- Impurities must also satisfy **charge balance = Electroneutrality**




- Substitutional cation impurity



initial geometry




Ca²⁺ impurity




resulting geometry


- Substitutional anion impurity



initial geometry




O²⁻ impurity



resulting geometry



Application-classification of Ceramics



- Properties:
 - T_m for glass is moderate, but large for other ceramics.
 - Small toughness, ductility; large moduli & creep resist.
- Applications:
 - High T , wear resistant, novel uses from charge neutrality.
- Fabrication
 - some glasses can be easily formed
 - other ceramics can not be formed or cast.



Compositions and characteristics of some of the common commercial glasses

<i>Glass Type</i>	<i>Composition (wt%)</i>						<i>Characteristics and Applications</i>
	<i>SiO₂</i>	<i>Na₂O</i>	<i>CaO</i>	<i>Al₂O₃</i>	<i>B₂O₃</i>	<i>Other</i>	
Fused silica	>99.5						High melting temperature, very low coefficient of expansion (thermally shock resistant)
96% Silica (Vycor™)	96				4		Thermally shock and chemically resistant—laboratory ware
Borosilicate (Pyrex™)	81	3.5		2.5	13		Thermally shock and chemically resistant—ovenware
Container (soda-lime)	74	16	5	1		4MgO	Low melting temperature, easily worked, also durable
Fiberglass	55		16	15	10	4MgO	Easily drawn into fibers—glass-resin composites
Optical flint	54	1				37PbO, 8K ₂ O	High density and high index of refraction—optical lenses
Glass-ceramic (Pyroceram™)	43.5	14		30	5.5	6.5TiO ₂ , 0.5As ₂ O ₃	Easily fabricated; strong; resists thermal shock—ovenware

- Optical transparency
- Relative ease to fabricate




Application: Die Blanks

- Die blanks:

- Need wear resistant properties!

SiC, WC, Al₂O₃, silica sand, etc

Courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.




Adapted from Fig. 11.8 (d), Callister 7e.

- Die surface:

- 4 μm polycrystalline diamond particles that are sintered onto a cemented tungsten carbide substrate.

- polycrystalline diamond helps control fracture and gives uniform hardness in all directions.



Courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.




Application: Cutting Tools

- Tools:
 - for grinding glass, tungsten, carbide, ceramics
 - for cutting Si wafers
 - for oil drilling
- Solutions:
 - manufactured single crystal or polycrystalline diamonds in a metal or resin matrix.
 - optional coatings (e.g., Ti to help diamonds bond to a Co matrix via alloying)
 - polycrystalline diamonds resharpen by microfracturing along crystalline planes.




oil drill bits



blades



coated single crystal diamonds





polycrystalline diamonds in a resin matrix.

Photos courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.



Application: Sensors

- Example: Oxygen sensor ZrO_2
- Principle: Make diffusion of ions fast for rapid response.
- Approach:
 - Add Ca impurity to ZrO_2 :
 - increases O^{2-} vacancies
 - increases O^{2-} diffusion rate
- Operation:
 - voltage difference produced when O^{2-} ions diffuse from the external surface of the sensor to the reference gas.




Ceramic Fabrication Methods-I

GLASS FORMING

PARTICULATE FORMING

CEMENTATION


- Pressing:




plates, dishes, cheap glasses

--mold is steel with graphite lining

- Blowing:



- Fiber drawing:




Adapted from Fig. 13.8, *Callister, 7e*. (Fig. 13.8 is adapted from C.J. Phillips, *Glass: The Miracle Maker*, Pittman Publishing Ltd., London.)



Sheet Glass Forming

- Sheet forming – continuous draw
 - originally sheet glass was made by “floating” glass on a pool of mercury



Adapted from Fig. 13.9, *Callister 7e*.



Ceramic Fabrication Methods-IIA


GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION



- Milling and screening: desired particle size
- Mixing particles & water: produces a "slip"
- Form a "green" component

--Hydroplastic forming:
extrude the slip (e.g., into a pipe)



Adapted from Fig. 11.8 (c), Callister 7e.

--Slip casting:




Adapted from Fig. 13.12, Callister 7e. (Fig. 13.12 is from W.D. Kingery, *Introduction to Ceramics*, John Wiley and Sons, Inc., 1960.)

- Dry and fire the component

Drying and Firing

- **Drying:** layer size and spacing decrease.



wet slip

partially dry


"green" ceramic

Drying too fast causes sample to warp or crack due to non-uniform shrinkage

- **Firing:**

-- T raised to (900-1400°C)

-- **vitrification:** liquid glass forms from clay and flows between SiO_2 particles. Flux melts at lower T .



Adapted from Fig. 13.14, *Callister 7e*. (Fig. 13.14 is courtesy H.G. Brinkies, Swinburne University of Technology, Hawthorn Campus, Hawthorn, Victoria, Australia.)



Ceramic Fabrication Methods-IIB


GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

Sintering: useful for both clay and non-clay compositions.

- Procedure:
 - produce ceramic and/or glass particles by grinding
 - place particles in mold
 - press at elevated T to reduce pore size.
- Aluminum oxide powder:
 - sintered at 1700°C for 6 minutes.



Adapted from Fig. 13.17, *Callister 7e*.
(Fig. 13.17 is from W.D. Kingery, H.K. Bowen, and D.R. Uhlmann, *Introduction to Ceramics*, 2nd ed., John Wiley and Sons, Inc., 1976, p. 483.)



Powder Pressing


Sintering - powder touches - forms neck & gradually neck thickens

- add processing aids to help form neck
- little or no plastic deformation

Uniaxial compression - compacted in single direction

Isostatic (hydrostatic) compression - pressure applied by fluid - powder in rubber envelope

Hot pressing - pressure + heat




Adapted from Fig. 13.16, *Callister 7e*.



Tape Casting

- thin sheets of green ceramic cast as flexible tape
- used for integrated circuits and capacitors
- cast from liquid slip (ceramic + organic solvent)



Adapted from Fig. 13.18, *Callister 7e*.



Ceramic Fabrication Methods-III

GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

- Produced in extremely large quantities.
- Portland cement:
 - mix clay and lime bearing materials
 - calcinate (heat to 1400°C)
 - primary constituents:
 - tri-calcium silicate
 - di-calcium silicate
- Adding water
 - produces a paste which hardens
 - hardening occurs due to hydration (chemical reactions with the water).
- Forming: done usually minutes after hydration begins.



Applications: Advanced Ceramics

Heat Engines

- Advantages:
 - Run at higher temperature
 - Excellent wear & corrosion resistance
 - Low frictional losses
 - Ability to operate without a cooling system
 - Low density
- Disadvantages:
 - Brittle
 - Too easy to have voids-weaken the engine
 - Difficult to machine
- Possible parts – engine block, piston coatings, jet engines
Ex: Si_3N_4 , SiC , & ZrO_2



Summary-2

- Ceramic materials have covalent & ionic bonding.
- Structures are based on:
 - charge neutrality
 - maximizing # of nearest oppositely charged neighbors.
- Structures may be predicted based on:
 - ratio of the cation and anion radii.
- Defects
 - must preserve charge neutrality
 - have a concentration that varies exponentially w/ T .
- Room T mechanical response is elastic, but fracture is brittle, with negligible deformation.
- processing and application

