CHAPTER 4: IMPERFECTIONS IN SOLIDS

ISSUES TO ADDRESS...


- · What are the solidification mechanisms?
- · What types of defects arise in solids?
- · Can the number and type of defects be varied and controlled?
- · How do defects affect material properties?
- · Are defects undesirable?





Imperfections in Solids


- Solidification- result of casting of molten material
 - 2 steps
 - Nuclei form
 - · Nuclei grow to form crystals grain structure
- Start with a molten material all liquid



Crystals grow until they meet each other



Polycrystalline Materials Angle of misalignment **Grain Boundaries** · regions between crystals High-angle _ grain boundary · transition from lattice of one region to that of the other Small-angle grain boundary slightly disordered low density in grain boundaries - high mobility - high diffusivity Angle of misalignment - high chemical reactivity Adapted from Fig. 4.7, Callister 7e. Chapter 4 - 3



There is no such thing as a perfect crystal.

- What are these imperfections?
- Why are they important?

Many of the important properties of materials are due to the presence of imperfections.





Types of Imperfections

- Vacancy atoms
- Interstitial atoms
- · Substitutional atoms


Point defects

Dislocations


- Line defects
- Grain Boundaries

Area defects











Measuring Activation Energy

- We can get Q_{ν} from an experiment.
- Measure this...
- $\frac{N_V}{N} = \exp\left(\frac{-Q_V}{kT}\right)$
- · Replot it...







Estimating Vacancy Concentration

- Find the equil. # of vacancies in 1 m³ of Cu at 1000°C.
- Given:

$$\rho = 8.4 \text{ g/cm}^3$$

$$A_{CIJ} = 63.5 \text{ g/mol}$$

$$Q_{V} = 0.9 \text{ eV/atom} \ N_{A} = 6.02 \text{ x } 10^{23} \text{ atoms/mol}$$

$$\frac{N_{V}}{N} = \exp\left(\frac{-Q_{V}}{kT}\right)^{0.9 \text{ eV/atom}} = 2.7 \text{ x } 10^{-4}$$

$$1273 \text{ K}$$

$$8.62 \text{ x } 10^{-5} \text{ eV/atom-K}$$
For 1 m³, $N = \rho$ x $\frac{N_{A}}{A_{Cu}}$ x 1 m³ = 8.0 x 10²⁸ sites


· Answer:


$$N_V = (2.7 \times 10^{-4})(8.0 \times 10^{28}) \text{ sites} = 2.2 \times 10^{25} \text{ vacancies}_{\text{Chapter 4 - 10}}$$

Observing Equilibrium Vacancy Conc.

- Low energy electron microscope view of a (110) surface of NiAl.
- Increasing *T* causes surface island of atoms to grow.
- Why? The equil. vacancy conc. increases via atom motion from the crystal to the surface, where they join the island.

Island grows/shrinks to maintain equil. vancancy conc. in the bulk.





Reprinted with permission from Nature (K.F. McCarty, J.A. Nobel, and N.C. Bartelt, "Vacancies in Solids and the Stability of Surface Morphology", Nature, Vol. 412, pp. 622-625 (2001). Image is 5.75 μm by 5.75 μm.) Copyright (2001) Macmillan Publishers, Ltd.







Point Defects in Alloys

Two outcomes if impurity (B) added to host (A):

• Solid solution of B in A (i.e., random dist. of point defects)




OR



(e.g., C in Fe)

 Solid solution of B in A plus particles of a new phase (usually for a larger amount of B)



Second phase particle

- --different composition
- -- often different structure.

Conditions for substitutional solid solution (S.S.)

- W. Hume Rothery rule
 - -1. Δr (atomic radius) < 15%
 - 2. Proximity in periodic table
 - · i.e., similar electronegativities
 - 3. Same crystal structure for pure metals
 - 4. Valency
 - · All else being equal, a metal will have a greater tendency to dissolve a metal of higher valency than one of lower valency





Imperfections in Solids

Application of Hume-Rothery rules - Solid Solutions

1. Would you predict more Al or Ag to dissolve in Zn?

2. More Zn or Al in Cu?

Element	Atomic Radius (nm)	Crystal Structure	Electro- nega- tivity	Valence
Cu C H O	0.1278 0.071 0.046 0.060	FCC	1.9	+2
Ag Al Co Cr Fe Ni Pd Zn	0.1445 0.1431 0.1253 0.1249 0.1241 0.1246 0.1376 0.1332	FCC FCC HCP BCC BCC FCC FCC HCP	1.9 1.5 1.8 1.6 1.8 1.8 2.2	+1 +3 +2 +3 +2 +2 +2 +2

Table on p. 106, Callister 7e.

- · Specification of composition
 - $C_1 = \frac{m_1}{m_1 + m_2} \times 100$ - weight percent

 m_1 = mass of component 1

 $C_1^{'} = \frac{n_{m1}}{n_{m1} + n_{m2}} \times 100$ - atom percent

 n_{m1} = number of moles of component 1




Line Defects

Dislocations:

- · are line defects,
- · slip between crystal planes result when dislocations move,
- produce permanent (plastic) deformation.

Schematic of Zinc (HCP):

- · before deformation
- · after tensile elongation




Adapted from Fig. 7.8, Callister 7e.




Linear Defects (Dislocations)

- Are one-dimensional defects around which atoms are misaligned
- Edge dislocation:
 - extra half-plane of atoms inserted in a crystal structure
 - **b** \perp to dislocation line
- Screw dislocation:
 - spiral planar ramp resulting from shear deformation
 - b || to dislocation line


Burger's vector, **b**: measure of lattice distortion





Motion of Edge Dislocation


- Dislocation motion requires the successive bumping of a half plane of atoms (from left to right here).
- · Bonds across the slipping planes are broken and remade in succession.




Atomic view of edge dislocation motion from left to right as a crystal is sheared.

(Courtesy P.M. Anderson)









Dislocations are visible in electron micrographs



Adapted from Fig. 4.6, Callister 7e.



Dislocations & Crystal Structures

• Structure: close-packed planes & directions are preferred.

view onto two close-packed planes.

close-packed directions

close-packed plane (bottom)

close-packed plane (top)


Comparison among crystal structures:

FCC: many close-packed planes/directions;

HCP: only one plane, 3 directions;


BCC: none

 Specimens that were tensile tested.



Planar Defects in Solids

- One case is a twin boundary (plane)
 - Essentially a reflection of atom positions across the twin plane.



- Stacking faults
 - For FCC metals an error in ABCABC packing sequence
 - Ex: ABCABABC




Microscopic Examination

- Crystallites (grains) and grain boundaries.
 Vary considerably in size. Can be quite large
 - ex: Large single crystal of quartz or diamond or Si
 - ex: Aluminum light post or garbage can see the individual grains
- Crystallites (grains) can be quite small (mm or less) – necessary to observe with a microscope.



Optical Microscopy

- · Useful up to 2000X magnification.
- Polishing removes surface features (e.g., scratches)
- Etching changes reflectance, depending on crystal orientation.





Micrograph of brass (a Cu-Zn alloy)



Optical Microscopy


Grain boundaries...


- · are imperfections,
- · are more susceptible to etching,
- · may be revealed as dark lines,
- · change in crystal orientation across boundary.

ASTM grain size number

$$N=2^{n-2}$$

number of grains/in2 at 100x magnification





Adapted from Fig. 4.14(a) and (b), Callister 7e. (Fig. 4.14(b) is courtesy of L.C. Smith and C. Brady, the National Bureau of Standards, Washington, DC [now the National Institute of Standards and Technology, Gaithersburg, MD].)

Chapter 4 - 27



Optical Microscopy

- · Polarized light
 - metallographic scopes often use polarized light to increase contrast
 - Also used for transparent samples such as polymers

Microscopy

Optical resolution ca. 10^{-7} m = 0.1 μ m = 100 nm For higher resolution need higher frequency

- X-Rays? Difficult to focus.
- Electrons
 - wavelengths ca. 3 pm (0.003 nm)
 - (Magnification 1,000,000X)
 - · Atomic resolution possible
 - Electron beam focused by magnetic lenses.



Scanning Tunneling Microscopy (STM)

· Atoms can be arranged and imaged!



Carbon monoxide molecules arranged on a platinum (111) surface.



Photos produced from the work of C.P. Lutz, Zeppenfeld, and D.M. Eigler. Reprinted with permission from International Business Machines Corporation, copyright 1995.

Iron atoms arranged on a copper (111) surface. These Kanji characters represent the word "atom".



Summary

- Point, Line, and Area defects exist in solids.
- The number and type of defects can be varied and controlled (e.g., T controls vacancy conc.)
- Defects affect material properties (e.g., grain boundaries control crystal slip).
- Defects may be desirable or undesirable (e.g., dislocations may be good or bad, depending on whether plastic deformation is desirable or not.)



